5

METHODOLOGY FOR CRITICAL DIMENSION METROLOGY USING STEPPER FOCUS MONITOR INFORMATION

ABSTRACT

A method of producing an accurate critical dimension measurement comprises navigating to a critical dimension structure, performing a scanning electron microscope focusing, performing a final location alignment, acquiring waveform data, analyzing the data to determine an approximate critical dimension, analyzing the data to determine a stepper focus parameter, combining the stepper focus parameter with the critical dimension to generate an accurate critical dimension value, and reporting the same.